
Tilly Mill Road at North Peachtree Road

malines the stillers will an

March 12, 2012



Gresham, Smith and Partners

Jay Bockisch, P.E., PTOEJody Braswell, P.E.











Presentation Agenda

Alternatives Considered Recommended Improvements Public Comments Other Considerations Traffic Simulation Next Steps



Alternatives Considered

Three Roundabout Alternatives Multiple roundabouts Combined roundabout – 5 legs Roundabout at Tilly Mill only **One Traditional Intersection Alternative** Turn lane improvements Peeler considerations



Multiple Roundabouts

- Closely spaced intersections
- Single lane due to spacing

Criteria		
Design Year LOS	F/C	
Cost	\$1,200,000	
Displacements	0	
Required ROW/Easements	0.5 acres	
	Queue spillback	
Operational	between	
Issues intersections		





Combined Roundabout

- 1 combined intersection
- 5 legs
- Multi-lane roundabout

Criteria		
Design Year LOS D		
Cost \$3,700,000		
Displacements	4	
Required ROW/Easements	1.5 acres	
Operational	Driver expectancy -	
Issues requires multi lanes		






Roundabout at Tilly Mill Only

- Roundabout at Tilly Mill
- Multi-lane roundabout
- Peeler stop sign controlled

Criteria		
Design Year LOS	D/F	
Cost \$2,300,000		
Displacements	1	
Required ROW/Easements	1.0 acres	
Operational Issues	Driver expectancy - requires multi lanes	






Traditional Turn Lanes

- Left and right turn lanes at each approach
- Turn lanes sized to accommodate queues

Criteria		
Design Year LOS	D/B	
Cost	\$1,600,000	
Displacements	0	
Required ROW/Easements	0.8 acres	
	Need to consider	
Operational	traffic control	
Issues options at Peeler		





Alternatives Considered


Criteria	Separate Roundabouts	Combined Roundabout	Roundabout at Tilly Mill	Traditional Turn Lanes
Design Year LOS	4 th	2 nd	3 rd	1 st
Cost	1 st	4 th	3rd	2 nd
Displacements	1 st	4 th	3rd	1 st
Required ROW/Easements	1 st	4 th	3rd	2 nd
Operational Issues	4 th	2 nd	3rd	1 st





Recommended Improvements

- Left and Right turn lanes at each approach
- Sidewalks
- Pedestrian crossings
- Continuous bike lanes
- Peach Roads Silver rated sustainable project
- Multiple traffic control options at Peeler Rd





Public Comments from PIOH

35 Provided Comments 19 Support / Conditionally Support 9 Uncommitted 7 Oppose **Comments/Concerns:** "Outside" traffic (college, other Cities) **Coordinated signals** Adequate turn lane lengths



11 Perimeter Center East, Suite 250 Durwoody, Georgia 30346 P (678) 382-6700 F(678) 382-6701 durwoodyga.gov

CITY OF DUNWOODY DEPARTMENT OF PUBLIC WORKS

Intersection of North Peachtree Road and Tilly Mill Road Safety and Operational Improvements

Public Information Open House January 19, 2012			
BACKGROUND:	The purpose of this project is to provide safety and operational improvements to the intersection of Tilly Mill Road with North Peachree Road and the intersection of Peeter Road with North Peachree Road through the addition of turning lanes, bicycle lanes, sidewalk, and traffic signals.		
PROJECT LIMITS:	The project limits extend along Tilly Mill Road 500 ft. west from the North Peachtere Road intervetion at Kingswood United Methodist Charch to 600 ft. east of the intervection. The limits of the project span along North Peachtere Road 300 ft. south of the Peeler Road intersection at Saint Barnabas Anglican Church to 400 ft. north of the Tilly Mill Road intersection. The project limits along Peeler Road begin 400 ft. west of the intersection with North Peachtere Road and end the intersection.		
PROJECT LENGTH:	The length of this project is 0.22 miles along Tilly Mill Road, 0.20 miles along North Peachtree Road, and 0.08 miles along Peeler Road.		
PROJECT SCOPE:	The project consists of improving both intersections with adding and lengthening left and right training lance on all approaches. Bicycle lanes (except on the North Re of North Pachtnere Road) and sidewalks will also be added on both sides of each roadway. A traffic signal will be placed at the intersection of North Pachtrere Road and Peeler Road in addition to the existing traffic signal at the intersection of Tilly Mill Road and North Pachtree Road.		
PROJECT SCHEDULE:	Right-of-Way: Fall 2012		

Construction: Summer 2013 Open to Traffic: Fall 2014 G S & P

Other Considerations

Comparison to Dunwoody Club Drive Traffic Control at Peeler Road



Issue #1: Comparison to Dunwoody Club

- Distance
- Traffic Volumes
- Turn Lanes & Capacity
- Traffic Signal Operations





Comparison to Dunwoody Club

Criteria	Dunwoody Club Area	North Peachtree / Tilly Mill	
Distance	Lower – 165'	Greater – 320'	
Traffic Volumes	Greater – 54,700 ADT	Lower – 47,300 ADT	
Turn Lanes & Capacity	Lower	Greater	
Traffic Signal Operations	Complex – 5 Legs	Simpler – 2 Coordinated Intersections	



Issue #2: Comparison of Traffic Control Options at Peeler Rd

Criteria	Stop Sign (Existing Condition)	Prohibited Lefts	Signalized Lefts
Traffic Diversions	Small decrease of traffic from Peeler due to delay	Significant diversions of lefts – no good alternative route	Minimal increase of traffic to Peeler
Enforcement	Self-Enforcing	Significant Enforcement Required	Self-Enforcing
Design Year Peak Hour Level of Service on Peeler	F	A	С
Safety	Less safe due to Safety minimal gaps in mainline traffic		Safer for Peeler – Potential for small increase in crashes along N Peachtree



Traffic Simulation



Presentation Agenda

Next StepsComplete ConceptBegin Final Design

